National Transportation Safety Board FACTUAL REPORT

NTSB ID: CHI96LA069 Aircraft Registration Number: N39244 Occurrence Date: 12/29/1995 Most Critical Injury: Serious Occurrence Type: Accident Investigated By: NTSB

Location/Time

Nearest City/Place State Zip Code Local Time Time Zone 1700 SD 57580 CST WINNER Distance From Landing Facility:

Airport Proximity: Off Airport/Airstrip

Aircraft Information Summary

Aircraft Manufacturer Model/Series Type of Aircraft **TAYLORCRAFT** BC-12 /BC-12 Airplane

Revenue Sightseeing Flight: No

Air Medical Transport Flight: No

Narrative

Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:

*** Note: NTSB investigators may not have traveled in support of this investigation and used data provided by various sources to prepare this aircraft accident report. ***

On December 29, 1995, at 1700 central standard time, a Taylorcraft BC-12, N39244, was substantially damaged when it lost control during takeoff climb and impacted the terrain near Winner, South Dakota. The pilot was seriously injured. The 14 CFR Part 91 flight had departed a stubble wheat field. The pilot had intended to land at Bob Riley Field, at Winner, South Dakota, which was about four miles away. Visual meteorological conditions prevailed at the time of the accident and no flight plan was filed.

The pilot reported that he had trouble getting the engine started since he had to pull the propeller through twenty times before it started. After the engine run-up he departed the field to the southeast. He reported that during the initial climb he felt that the engine was not giving quite the full power he expected.

During a telephone conversation, the pilot reported that he tried to check the magnetos and carburetor heat during the takeoff climb. He stated that he was not paying attention to what he was doing, and that he, "...basically just stalled it and spun it into the ground." He reported that it was pilot error without a doubt, and that he could have flown it down to the ground.

He reported that he had owned the airplane for about a month. He had 30 hours total time in the airplane which included 10 hours of dual flight time.

A witness reported that the wing and tail section were vibrating "pretty rough" during the takeoff from the stubble field. The witness reported that the airplane got up in the air pretty fast and did not use more than 100 yards during the ground run. He reported that the airplane banked hard left, and then cut back hard to the right before it went straight over and nosed straight in. The witness reported that the airplane had climbed about 150 feet.

An Airworthiness Inspector from the Federal Aviation Administration examined the wreakage. He reported that after initial liftoff the airplane settled down near the ground, and then climbed in a nose high attitude. He reported that the aircraft stalled, spun, and impacted the ground almost vertically straight down. The highest altitude gained was 150 to 200 feet above ground level.

The engine was examined and it had continuity and the compression checked normal. The wooden propeller was splintered and only about 16 inches of the propeller remained intact.

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: CHI96LA069

Occurrence Date: 12/29/1995

AVIATION Occurrence Ty				Accident							
Landing Facility/Approach Inf	formation										
Airport Name Airp				Airport Elevation					n Ru	ınway Width	
				Ft. MSL	_ 0						
Runway Surface Type:											
Runway Surface Condition:											
Approach/Arrival Flown: NONE	Ē										
VFR Approach/Landing: None											
Aircraft Information											
Aircraft Manufacturer TAYLORCRAFT			Model/ BC-12					Serial N 6498	Number		
Airworthiness Certificate(s): Normal											
Landing Gear Type: Tailwheel											
Amateur Built Acft? No								r of Engin	es: 1		
				nufacturer: ENTAL	Model/Sei A65-8				ated Power: 5 HP		
- Aircraft Inspection Information											
Type of Last Inspection	Date of Last Inspection Til			nce Last Inspe	ection		Airframe ¹	Total Time			
Annual		0	1/1995				73 Ho	urs		2434 Hours	
- Emergency Locator Transmitter (I	ELT) Information										
ELT Installed?/Type Yes / ELT Operated? Yes ELT Aided in Locating Accident Site? No											
Owner/Operator Information											
Registered Aircraft Owner Street Address 300 SW 8TH BOX A-1											
MONTE L. HAY			City MADISON							Zip Code 57042	
			Street A								
•	Operator of Aircraft 300 SW 8TH BOX A-1 City State Zip Co								Zip Code		
MONTE L. HAY City MADISON					SD 57042					1 '	
Operator Does Business As: Operator Designator Code:											
- Type of U.S. Certificate(s) Held: N	None										
Air Carrier Operating Certificate(s):	:										
Operating Certificate:				Operator Certific	cate:						
Regulation Flight Conducted Under	er: Part 91: Genera	al Aviation									
Type of Flight Operation Conducted	d: Personal										
	J	FACTUA!	L REPO	RT - AVIATION						Page 2	

National Transportation Safety Board FACTUAL REPORT AVIATION

NTSB ID: CHI96LA069

Occurrence Date: 12/29/1995

	AVIATI	Occurrence Type: Accident]								
First Pilot	t Information													
Name						City				S	State	Date	e of Birth	Age
On File						ile			0	n File			29	
Sex: M	Sex: M Seat Occupied: Front Occupational Pilot? Unknown Certificate Number:													
Certificate(s): Priva	ate	'											
Airplane Ra	ating(s): Sing	le-engine L	and											
Rotorcraft/0	Glider/LTA: None	<u> </u>												
Instrument	Rating(s): None	<u> </u>												
Instructor F	Rating(s): None	е												
Current Bie	nnial Flight Revie	ew?												
Medical Ce	ert.: Class 3	Medica	al Cert. Statu	s: Valid Me	dicalw/ w	aivers/	lim.		Date	of Last	Medical	Exam:	: 12/1994	
		I												
- Flight Tim	ne Matrix	All A/C	This Make and Model	Airplane Single Engine	Rotorcraft Glider						Lighter Than Air			
Total Time		98	28	98			5			3				
Pilot In Cor	mmand(PIC)					_								
Instructor												_		
Instruction						+						_		
Last 90 Da		35	28	35		+								
Last 30 Day		10	10	10		+						-+		
Last 24 Ho		Shoul	Ilder Harness	JIsad? No			Toxico	logy Perf	Performed? No Secon			Second	d Pilot? No	<u> </u>
	Seatbelt Used? Yes Shoulder Harness Used? No Toxicology Performed? No Second Pilot? No								,					
	in/Itinerary													
	ght Plan Filed: No	one					I a				Τ,			T' 7
Departure Point Same as Accident/Incident Location							State Airpor		rport Ide			Departure Time 1700		Time Zone CST
Destination	1						State	Λ.	irport Ido	ntifior				
WINNER AIRPORT							SD		Airport Identifier SD39					
Type of Cle	earance: None													
Type of Air	space: Class	G												
Weather	Information													
Úa∥io©ÁSou	rce of Wx Informa	ation:												
	No rec	ord of briefi	ng											
				FACTUAL	REPORT	- AVI	ATION	N						Page 3

National Transportation Safety Board
FACTUAL REPORT

NTSB ID: CHI96LA069

Occurrence Date: 12/29/1995

AVIATION			Oc	Occurrence Type: Accident											
Weather	Information								•						
WOF ID	Observation Time	Time Zone	WOF	WOF Elevation V			WOF Distance From Accident Site				Direction From Accident Site				
	!														
VTN	1656	CST		579 Ft. MSL	╧				50 NM			210 🗅	eg. Mag.		
Sky/Lowes	st Cloud Condition: Clear	<u> </u>					0 Ft. A0	GL	Condition o	of Ligh	nt: Day				
Lowest Cei	eiling: None			0 Ft. AGL		Visibility: 10			SM	Alti	meter:	29.00	"Hg		
Temperature: 4 °C Dew Point: -11 °C				1 °C We	eath	er Condi	tions at Acc	cident S	site: Visual (Conc	ditions				
Wind Direc	etion: 350	Wind Sp	eed: 4			Winc	d Gusts:								
Visibility (R	RVR): 0 Ft.	Visibility	/ (RVV)	0 SM	1										
Precip and	d/or Obscuration:														
Accident	Accident Information														
Aircraft Dar	mage: Substantial		Airc	raft Fire: No	ne				Aircraft Exp	losio	n None				
Alloran Da.	- Tiago. Oubstantiai								Alloran Eng	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	11 140110				
					<u> </u>			\top							
	mmary Matrix	Fatal	Serious	Minor	<u> </u>	None	TOTAL	-							
First Pil			1	$\vdash \vdash \vdash$	\vdash		1	4							
Second				\vdash	\vdash			-							
Student				\vdash	\vdash			4							
	nstructor				\vdash			4							
Check F				$\vdash \vdash \vdash$	\vdash			-							
	Engineer			$\vdash \vdash \vdash$	\vdash			-							
	Attendants			$\vdash \vdash \vdash$	\vdash			-							
Other C			!		\vdash			_							
Passen					\vdash			-							
- TOTAL A			1		<u> </u>		1	┥							
Other G		0	0		-		C	┥							
- GRAND	D TOTAL -	0	1	0	\bot		1	1							

National Transportation Safety Board

FACTUAL REPORT AVIATION NTSB ID: CHI96LA069

Occurrence Date: 12/29/1995

Occurrence Type: Accident

istrative	

Investigator-In-Charge (IIC)

JAMES P. SILLIMAN

Additional Persons Participating in This Accident/Incident Investigation:

PETE SHOULDIS RAPID CITY, SD